

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☐

Name of Operator

SHELL OIL COMPANY

Address of Operator

P. O. BOX 991, HOUSTON, TX 77001

Location of Well

UNIT LETTER H 990 FEET FROM THE EAST LINE AND 2310 FEET FROM
THE NORTH LINE, SECTION 29 TOWNSHIP 18S RANGE 38E N.M.P.M.

7. Unit Agreement Name

8. Field or Lease Name

TIDEWATER-GRIMES

9. Well No.

2

10. Field and Pool, or Wildcat

HOBBS (G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)

3650' GL

12. County

LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPERATIONS ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-25-81: Dug out cellar.

2-27-81: Drld cmt from around 2 7/8" dry hole marker inside 16" csg.

3/3-4/81: Drld 8' cmt + 1' wooden plug inside 16" csg w/14 3/4" bit. Drld down 285' through cmt, wooden plug, and red bed w/12 1/4" bit. Bottom 16" csg @230'.

3-8-81: Pumped 100 sx Class "C" to plug leaks in conductor pipe. Drld and circ hole to 1197'; top of 9 5/8" @1197'.

3-12-81: Tried to get inside 9 5/8" csg with bits and mills but unable to. Drld outside of 9 5/8" down to 1300' where a hole was made in side of 9 5/8" csg. Drld to 1351' inside of 9 5/8". POH.

3-31-81: RIH w/ 4 5/8" bit and drilled and circ to 1361' (outside of 9 5/8"); unable to get into window (hole) in 9 5/8" @ 1300'. POH.

4-7-81: Loaded hole w/mud to the surface, RD. Installed a 16" female casing protector on top of 16" csg. Welded a 3" plate over the top of the protector w/ 1 - 1" lug on opposite side of the plate for removal.

4-8-81: Well plugged and abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

A. J. FORE

TITLE SUPERVISOR REG./PERMITTING

DATE 4-23-81

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: