

OIL CONSERVATION COMMISSION

DUPLICATE MISCELLANEOUS REPORTS ON WELLS

Santa Fe, New Mexico

RECEIVED
MAR 31 1947
RECEIVED
HOBBS OFFICE

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	X	REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

March 28, 1947

Monument, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____
America Petroleum Corporation H. I. McKinley Well No. 6 in the _____
Company or Operator Lease

NE 1/4 of Sec. 34, T. 18S, R. 22E, N. M. P. M.,
Bowers Field, Lea County.

The dates of this work were as follows: March 20th to 23rd, 1947.

Notice of intention to do the work was (~~was not~~) submitted on Form C-102 on March 19, 1947 19____
and approval of the proposed plan was (~~was not~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

3223' Test 1 Depth Anhydrite and Lime, Shot with 3. Quarts Nitroglycerine, 4" Tin Shell from 3205-17, A. C. Timb Bomb, Bolshevik Cave Catcher and tamped with 1 Yard Pea Gravel, shot went off at 12 noon March 20th., 1947, and well did not flow, went in hole with tubing and found to 32' bridge at 3239' and finished cleaning out to bottom at 13;15PM March 22, 1947, Ran 104 ft 2" EUE 4.74, J-55, 8 RT Spring Seamless Steel Tubing and set at 3'13' perforated nipple on bottom bull plugged and 1-4" Sub on top, and testing nipple set at 3209'. Swabbed into pits 3 hour estimate of 10 barrels and swabbed into tanks for 24 hours and made 67.52 barrels oil 24 hours. Will test further.

Witnessed by W. D. Jarred Name _____ Company _____ Foreman _____
Title _____

Subscribed and sworn before me this _____

I hereby swear or affirm that the information given above is true and correct.

28 day of March, 19 47

Name _____

Position _____ Asst. Dist. Supt.

Representing _____
Company or Operator

My commission expires _____

Address _____ D. L. L. Monument, New Mexico.

Remarks:

APPROVED

Date MAR 31 1947

Ray Garbary
Name _____
Oil & Gas Inspector
Title _____