

Form 10-331a
(March 1942)

Revised Bureau No. 42-5328
Approval expires 12-30-47

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces, N.M.

Lease No. 032233-A

Unit _____

E. A. Powers "A" - Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REPAIR REPAIR WELL <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas August 26, 1947

Well No. A-1 is located 330 ft. from N line and 290 ft. from E line of sec. _____
SE 1 of 30 16-S 38-E R.P.
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Lea New Mexico
(County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(Give names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Work to consist of cementing behind corroded 5" casing, replacing 3" tubing with 2" tubing, and repairing well connections.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company Oil & Gas Company

Address Box 1500
Midland, Texas

By: [Signature]
Title Assistant Division Superintendent