

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces, N. Mex.

Lease No. 21027 032233 A

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

B. A. Bowers "A" (Federal)

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas July 7, 1947

Well No. A-13 is located 1980 ft. from N line and 1980 ft. from E line of sec. 30

N₁/4 of SE/4 of Sec. 30
(1/4 Sec. and Sec. No.)

18-6 38-E
(Twp.) (Range)

(Meridian)

Bowers

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)


The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

8-5/8" casing tested with 700# pressure at 6:40 PM 7-3-47. Tested OK. Drilled plug at 7:30 AM 7-4-47.

*3 5/8" cemented @ 283' w/ 125 sacks
on 7-2-47*



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Co.

Address Box 1600

Midland, Texas

By [Signature]
Title Acting Division Superintendent