331 a 942)		Approval expires 11-30-46.
	(SUBMIT IN TRIPLICATE)	Land Office
	UNITED STATES	Lease Mp50 [1 0 947
	DEPARTMENT OF THE INTERIOR	
	GEOLOGICAL SURVEY	Powars BBS CARINGE

Budget Bureau No. 42-R358.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLA NOTICE OF INTENTION TO TEST WATER NOTICE OF INTENTION TO RE-DRILL OR NOTICE OF INTENTION TO SHOOT OR AN	NS SHUT-OFF REPAIR WELL	SUBSEQUENT REPORT OF SHO SUBSEQUENT REPORT OF ALT SUBSEQUENT REPORT OF RED SUBSEQUENT REPORT OF ADA	OTING OR ACIDIZING ERING CASING RILLING OR REPAIR	
NOTICE OF INTENTION TO PULL OR ALT NOTICE OF INTENTION TO ABANDON WE	LL	SUPPLEMENTARY WELL HISTO	RY	
	-	llichana, Texas	July 7,	/ /
Well No. 1-13 is loca 11 /4 of 31/4 of 30c. 30 (4 Sec. and Sec. No.)	18-3	38-3		30 ec
(Field)	l.or.		n) SW MORT ICO (State or Territory)	

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8-5/8" casing tested with 7000 pressure as 6:40 of 2-5-47. souther at. rilled plug at 7:50 as 7-4-47.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company_	Humble Oil & Bfining to.	
Address	bex 1600	
	licland, ex.s	* Hukuan
*		Title