


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, August 23, 1947

Well No. A-15 is located 480 ft. from N line and 630 ft. from E line of sec. 30
SE 1/4 of SE 1/4 of Sec. 30 18-S 18-E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bowers Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3646 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 11" surface hole at 4 AM 8-22-47. Set 8-5/8" casing as follows:

Size	Amount	Weight	Set at	Formation	Total depth of well	No. Sacks Make Cement	Plug on Bottom
8-5/8"	237.69'	28#	248.59'	Red Beds	260'	150 sacks Atlas Reg.	4:30 PM 8-22-47

Halliburton Method used.

Circulated and pumped out approx. 60 sacks cement.

Will test casing with 800# pressure at 4:30 PM 8-23-47.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Co.

Address Box 1600

Midland, Texas

By [Signature]

Title Assistant Division Superintendent