

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410C CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-07522
5. Indicate Type of Lease
STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	7. Lease Name or Unit Agreement Name W.D. Grimes NCT-A
2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 4
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Pool name or Wildcat Bowers Seven Rivers
4. Well Location Unit Letter C : 330 Feet From The North Line and 2310 Feet From The West Line Section 32 Township 18S Range 38E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NDWH NUBOPE RU WLU & CAP CIBP, PREVIOUSLY SET @ 3078 W/35' CMT, TIH W/BIT & SCRAPER TO 2712 RU WLU & PERF 7" CSG @ 2792' TIH W/CICR & SET @ 2696, ATTEMPT TO SQUEEZE PERFS @ 2792, COULD NOT PUMP INTO FORMATION @ 3500 PSI, CIRC WELLBORE W/P&A MUD ABOVE CICR, SPOT 50 SX CMT PLUG F 2696 TO 2360, SPOT 50 SX CMT PLUG F 1308 TO 1058, PERF 7" & 9 5/8" CSG @ 270', NU WH, ESTABLISH CIRC UP 9 5/8 X 15 1/2" ANNULUS CMT'D 9 5/8" X 15 1/2" ANNULUS W/400 SX CMT, CLOSE VALVES @ WH & SQUEEZED 50 SX INTO FORMATION, NO BLOW ON 7" X 9 5/8" ANNULUS, MIX PUMP 50 SXS DN 9 5/8" X 7" ANNULUS, DIG OUT CELLAR, CUT OFF WELLHEAD 3' BELOW GL, INSTALL DRYHOLE MARKER, CHANGE WELL STATUS TO PLUGGED & ABANDONED 12-01-89.

WORK STARTED 11-30-89

WORK ENDED 12-01-89

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins

TITLE Staff Drlg. Engr.

DATE 12-05-89

TYPE OR PRINT NAME M.E. Akins

TELEPHONE NO. 393-4121

(This space for State Use)

APPROVED BY

OIL & GAS INSPECTOR

DATE JAN 10 1990

CONDITIONS OF APPROVAL, IF ANY: