

DUPLICATE

(Form
(Revised

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

July 13, 1953

(Date)

Midland, Texas

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Blackwood & Nichols Co. (Company or Operator) Carter (Lease)

Western Service Drilling Co. (Contractor), Well No. 1 in the S. 4. 1/4 Sec. 5

T18 S, R 39 E, NMPM, Wildcat Pool, Lea County.

The Dates of this work were as follows: July 10, 1953

Notice of intention to do the work (was not) submitted on Form C-102 on ---, 19---

(Cross out incorrect words)

and approval of the proposed plan (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

10 3/4" 32.75# 4-40 surface casing set at 297' and circulated cement with 200 ex. 14 gal. Plug down 1:30 P.M., July 10, 1953

Casing tested OK with 1000 psi for 30 min July 11, 1953

Witnessed by John Cambren (Name) Western Service Drilling Co. (Company) Tool Pusher (Title)

Approved: OIL CONSERVATION COMMISSION

Ray Garbrough (Name) Gas Inspector (Title)

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name C. H. Webb

Position Production Supt.

Representing Blackwood & Nichols Co.

Address 829 Republic Bldg., Midland, Texas