

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Bishop Canyon Uranium Corporation, Box 2016, Hobbs, New Mexico
(Address)

LEASE Hardin WELL NO. 1 UNIT 3 S 6 T 18 R 39

DATE WORK PERFORMED _____ POOL Wildcat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☒ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

5 1/2 csg. Left from 4475' to 3912'. Set cement plug @ 3900. Mud from 3900 to 2100 or Rustler formation. Cement plug from 2100' to 2050'. Mud from 2050' to 20'. Cement to surface with 4" X 4'. Reentered old hole. Tested queen. Still dry.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Robert H. [Signature]

Name [Signature]

Title _____

Position Secretary-Treasurer

Date _____

Company Bishop Canyon Uranium Corporation