NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Report by Chec	king Belov	W	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TES OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	ı .	REPORT ON (Other)	
	(2400)		3 Hobbs, New	Mexico
Following is a report on the work	done and the results obtained under the l	neading no	oted above at the	
MORRIS R.	ANTWE IL		Davis (Lease)	
Makin Dril	ling Company , Well No		in the 1/4 344 4	or Sec,
- 185 p 39 E NMPM	East Hobbs F	ool,	Lea	County
1	February 23 and 24,	1953.		
The Dates of this work were as follows:	3	Tak.		19 53
Notice of intention to do the work (wa	us) (*** submitted on Form C-10 on	reD	(Cross out incorrect words)	10
and approval of the proposed plan (wa	as) (zaza) obtained.			
DETA	ALLED ACCOUNT OF WORK DONE AN			
Set 79 joints of (9° distance from 300 sacks common	1857, 85/8" CD, 32# n bead to table). Cemer	smls.	casing at 1866 y plug method wit	:S.
Set 79 joints of (9' distance from 300 sacks common Tested casing for No loss is press Witnessed by J. W. Adm	1.857', 85/8" CD, 32# In bead to table). Cemer cement. In water shut off with large. WSO, O.K. Test many of the company. In hereby to the company. Name. Position	onls. on	casing at 1866 y plug method with the information given above is knowledge.	es.
Set 79 joints of (9° distance from 300 sacks common Tested casing for No loss is pressor Witnessed by J. W. Adm	1857', 85/8" CD, 324 n bead to table). Cemer cement. r water shut off with 1 ure. WSO, O.K. Test many (Company) N COMMISSION I hereb to the control of	onls. on	casing at 1866 y plug method with the information given above in the information given give	is true and comple