	State of New Mo ergy, Minerals and Natural Ro	exico esources Depart t	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210	OIL CONSERVATIO 2040 Pacheco Santa Fe, N	DN DIVISION St. M 87505	WELL API NO. 30-025-07944 5. Indicate Type of Lease STATE FEE L
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON WE	LLS	
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN RVOR. USE "APPLICATION FOR PE -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL OAS	OTHER		Carrie O. Davis
2. Name of Operator			8. Well Na
EnerQuest Resources,	LLC		2
3. Address of Operator		9. Pool name or Wildcat	
P. O. Box 11150, Mid	land, TX 79702		E. Hobbs (San Andres)
P. O. Box 11150, Mid. 4. Well Location Unit Letter <u>L</u> : <u>194</u>	80 Feet From The	Line and660	Feet From The L
P. O. Box 11150, Mid. 4. Well Location	80 Feet From The	ange 39E	Feet From TheU
P. O. Box 11150, Mid. 4. Well Location Unit Letter <u>L</u> : <u>194</u>	80 Feet From The <u>south</u> Township 18S R	ange 39E	Feet From The L
P. O. Box 11150, Mid. 4. Well Location Unit Letter	80 Feet From The <u>south</u> Township 18S R 10. Elevation (Show whether 359	ange 39E <i>DF, RKB, RT, GR, etc.)</i> 96' GR	Feet From The Lea Loa Lea Loa LoaLoa Loa Loa Loa _
P. O. Box 11150, Mid. 4. Well Location Unit Letter	80 Feet From The <u>south</u> Township 18S R 10. Elevation (Show whether 359 Appropriate Box to Indicate	ange 39E DF, RKB, RT, GR, etc.) 96' GR Nature of Notice, F	Feet From The Lea Lea
P. O. Box 11150, Mid. 4. Well Location Unit Letter	80 Feet From The <u>south</u> Township 18S R 10. Elevation (Show whether 359 Appropriate Box to Indicate	ange 39E DF, RKB, RT, GR, etc.) 96' GR Nature of Notice, F	Feet From The Lea Low Lea Low Lea County Report, or Other Data
P. O. Box 11150, Mid. 4. Well Location Unit Letter L : 199 Section 29 11. Check NOTICE OF IN	80 Feet From The <u>south</u> Township 18S R 10. Elevation (Show whether 359 Appropriate Box to Indicate TENTION TO:	ange 39E DF, RKB, RT, GR, etc.) 06' GR Nature of Notice, F SUE	Feet From The West L NMPM Lea County Report, or Other Data SEQUENT REPORT OF: ALTERING CASING
P. O. Box 11150, Mid. 4. Well Location Unit LetterL : Section 29 11. Check NOTICE OF IN PERFORM REMEDIAL WORK	80 Feet From The south Township 18S R 10. Elevation (Show whether 359 Appropriate Box to Indicate TENTION TO: PLUG AND ABANDON	ange 39E DF, RKB, RT, GR, etc.) 16' GR Nature of Notice, F SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C	Feet From The West L NMPM Lea County Report, or Other Data County BSEQUENT REPORT OF: Image: County of the second s

SEE ATTACHED DETAILED REPORT FOR PERIOD 6-10-97 through 6-20-97

I hereby certify that the information above is true and complete to the best of my knowled SKINATURE Christopher P. Renaud	odge mod belief. TITLE VP/Engineering	date <u>7-03-97</u> (915) telephone no. <u>685-3116</u>
(The spece for State Use) OHIGINAL SIGNED BY CHRIS WILLIAMS DISTRICT I SUPERVISOR		S. 26 1 17
APPROVED BY	TITLE	DATE

ENERQUEST RESOURCES, LLC

DAILY WORKOVER REPORT

Well Name: C. O. Davis No. 2	Operator: EnerQuest Resources, LLC	
Location: UL L, 1980' FSL & 660' FWL Sec. 29, T-18-S, R-39-E Lea County, NM	Project: E. Hobbs (San Andres) San Andres Deepening	
Elevation: 3,597' GL 3,603' KB	Contractor: Pool Company Denver City, TX	

<u>1997</u>

06-10: MIRUSU. Unflange tbg head & attempt to unseat tbg anchor. Could not get TAC loose. Rig up Rotary Wireline Co. & shoot 2 3/8" tbg loose @ 4362'. NUBOP.
POH w/ 2 3/8" tbg. RIH w/ 4 3/4" x 2 3/8" body catch overshot, bumper sub, hyd jars, 6-3 1/2" DC's, & accelerator sub w/ 2 7/8" workstring. Tagged up @ 3606' KB. Got stuck twice trying to get down. POH. RIH w/ 4 3/4" bit & csg scraper to 4340' KB. Rotated thru scale @ 4606' - 4630'. POH. Close well in & SDON. (Pulled 139 jts 2 3/8" tbg & 1-10' piece of cut off 2 3/8"). Prep to attempt to fish stuck TAC in am. DWC: \$6,042

06-11: RIH w/ 4 3/4" OD overshot. Could not get past 3637'. POH. RIH w/4" OD overshot. Catch fish @ 4362' & jar 1 1/2 hrs. Fish came loose. POH w/20' cut off jt tbg, 18' tbg pump bbl, 4' perf sub & 31' mud anchor joint. RIH w/ 4 3/4" mill tooth bit, 12- 3 1/2" DC's & 2 7/8" work string. Tag soft fill @ 4469'. Pull bit up to 4380' & mix mud & LCM. Pumped 240 bbls mud before breaking circ. Drill new formation from 4470-4473. Circ hole clean. Pull up 4 stands & SIWON. Prep to TOH in am & install button bit to commence deepening operations.

DWC: \$8,976 CWC: \$15,018

06-13: (24 hr report: 7:00 am 6-12 to 7:00 am 6-13) POH w/ 2 7/8" workstring, 12-3 1/2" DC's & 2 7/8" workstring. Had collar & bit plugged w/LCM. RIH w/new 4 3/4" "GT" Type 33 button bit (full open bore-no jets), bit sub, 12-3 1/2" DC's, xoversub & 2 7/8" work string. Tag fill @ 4430'. Mix mud to 10 ppg, 35 Vis, 6.8 WL. Break circ & displace LCM mud. WTB to depth of 4473' & commence drilling. Drill new hole to 4698' TD. Lost 800 bbls of starch/brine mud while drlg. Circ 2 hrs @ TD & POH w/workstring. Prep to run OH logs.

DWC: \$15,009 CWC: \$30,037

06-13: (Daylight Report) Rig up Halliburton. Run Spectral GR-DLL-CNL-LDT OH logs. Rig down Halliburton & SD for day. Release well service crew until 06-14. Prep to LD work string & move to Rocket Cain No. 1 in am.

- DWC: \$7,920 CWC: \$37,957
- 06-14: Open up BOP & bleed off gas pressure for 15 minutes. RIH w/DC's & LD same. RIH w/ 2 7/8" workstring & LD same. NDBOP & flange up wellhead. WO completion unit. Move all reverse equipment & rental equipment to Rocket Cain #1 location. Move well service unit to Rocket Cain location. DWC: \$2.065 CWC: \$40,022
- 06-18: MIRUSU. Prep to run in hole w/ 2 7/8" tbg in am & circ hole clean. DWC: \$130 CWC: \$40,152

Page 2 EnerQuest Resources, LLC C. O. Davis No. 2 Sec. 29, T-18-S, R-39-E Lea County, NM

DAILY WORKOVER REPORT

<u>1997</u>

06-19: Set pipe racks & unload & tally 2 7/8" production string. RIH w/"mule shoed" jt of 2 7/8" tbg, SN & production string to 4640'. Circ. hole clean using 450 bbls 9# brine. Lost approx 200 bbls water to formation. POH. Unload rod string from truck. RIH w/production tubing as follows:

1 - 2 7/8" x 32' BPMA @ 4451.33'

1 - 2 7/8" x 4' perf sub

1 - 2 7/8" SN @ 4419'

6 joints 2 7/8" tubing

1 - 2 7/8" x 5 1/2" TAC @ 4255'

136 joints 2 7/8" tubing

NDBOP & set TAC w/15 points. Flange up tbg head. Secure well & SDON. Prep to run rods & pump in am. DWC: \$23,543 CWC: \$63,695

06-20: RIH w/rods & pump as follows:

1 - 1 1/4" x 8' gas anchor

1 - 2 1/2" x 2" x 18' RHBC pump

1 - 7/8" x 26K shear tool

12 - 7/8" Norris 78 rods

52 - 3/4" Norris 78 rods

40 - 7/8" Norris 78 rods

47 - 1" Norris Fiberglass rods

1 - 1 1/2" x 22' polish rod w/1 3/4" x 12' liner.

Hang on & space out pump. Load & test tbg to 500 psi ok. Release service unit. Use gang to tie in flowline & repair flowline leaks. Start well pumping to tank battery @ 6:30 pm CST.

DWC: \$16,335

CWC: \$80,030