

Form 9-331a
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. LC 065078

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 15, 1947

Well No. Brown 1 is located 550 ft. from [N] line and 550 ft. from [E] line of sec. 6

Mulino Sec 6 12 9 32 E 4. 11. 2. W.
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Unnamed Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3655 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per our telephone conversation of Dec. 10th, 1947 we ran 1049 feet of 40 Lb., 8 5/8" Csg. and cemented with 50 sacks of cement and after circulating with mud. We allowed cement to set 72 Hrs. before drilling plug. After drilling out cement plug we tested for water shut-off by the bailing method. No water appeared after testing for 6 Hours. Drilling operations were resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company A.K. Poliss

Address C/O W.D. Paul

601 W. Quay, Artesia, N.M.

By W.D. Paul
W.D.M.

Title Agent