

Indian Agency.....

Allottee.....

Lease No.....

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYU. S. Land Office Las CrucesLease or permit No. 060967

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE OR OTHER DATA)

U. S. Minerals

February 1, 1944

19

Well No. 3 is located 660 ft. from IX line and 660 ft. from E line of sec. 30SE/4 30
(1/4 Sec. and Sec. No.)17S
(Twp.)33E
(Range)N.M.P.M.
(Meridian)Maljamar
(Field)Lea

(County or Subdivision)

New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 4041 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 1245 - Anhydrite - Run and cement 48 joints, 1051.85' of 8-5/8" 32#
 LW casing with 450 sacks regular and 100 sacks Incon
 cement and 6 sacks aquagel. Will test casing shut
 off 2-4-44

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum CompanyAddress Box 6666 Odessa, TexasBy /s/ H. R. PolsonTitle Chief Clerk