

APPROVED

MAR 20 1963

RONNIE E. SHOOK  
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Albuquerque  
Lease No. 0275774  
Unit 2

RECEIVED

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

Continuation of Drilling Operations

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Flaming Unit

March 23, 1963

Well No. 2 is located 3980 ft. from N line and 660 ft. from W line of sec. 28

S. 1/4 - NE 1/4, Sec. 28

(1/4 Sec. and Sec. No.)

T-29-S, R-32-E

(Twp.)

(Range)

N 100 W

(Meridian)

Lea County

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is N/A ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Sharp Drilling Co., Midland, Texas, spudded 17-1/2" hole at 2-30 PM, on 3-19-63. On 3-20-63, 15-3/8" OD 48# I-40 ST&C Casing was run and set at 773' with 750 gal. cement circulated. After 200 28 hours tested casing with 750 PSI for 30 minutes with no loss in pressure. Reduced hole to 12-1/4" at 773 and resumed drilling operations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum CorporationAddress Post Office Box 63Habba, New MexicoOriginal Signed by:  
V. E. STALEY

By

Title Area Superintendent

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office New Mexico  
0175774  
Lease No. 0175774  
Unit 8

RECEIVED

MAR 20 AM 8 47

1963

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
<u>Notice of change in operator</u> <input checked="" type="checkbox"/>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 19, 1963

## Plains Unit

Well No. 2 is located 1980 ft. from N line and 640 ft. from W line of sec. 28SW/4, NW/4 - Sec. 28 T-19-S, R-32-E NM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)East Maricao Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is NYA ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This form filed to change name of operator from Perry R. Bass, Fort Worth, Texas  
to Pan American Petroleum Corporation.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum CorporationAddress Post Office Box 68El Paso, New Mexico

By \_\_\_\_\_

Title Area Superintendent