



(SUBMIT IN TRIPLICATE)

Land Office New Mexico

Lease No. 025566

Unit Lusk Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1963 JUL 5 AM 8:16

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Cores.....	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 1, 1963

Well No. 5 is located 1980 ft. from N line and 1980 ft. from E line of sec. 19

SE/4 19 19 S 32 E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Lusk Deep-Strawn-Morrow Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3550 ft. GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 5/22/63: Core #1, 11,180' to 11,225'. Recovered 31.7', 7.5' black shale, 12.5' dense limestone, 5' brown limestone, 3' black shale, 3.7' grey limestone w/scattered vurgular porosity.

5/23/63: Core #2, 11,225' to 11,258'. Recovered 26', 2' brown limestone w/vurgular, 3'dense lime, 13' brown medium to coarse crystalline limestone w/good porosity, 8' dense limestone.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address P. O. Box 1492

El Paso 99, Texas

Att: Drilling Department

CREATED BY

By E. J. COEL

Title