

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103

HOBBS OFFICE (Rev. 3-55) O.C.C.

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Nov 12 9 06 AM '63

Name of Company DOB Oil Properties, Inc.				Address Box 953, Midland, Texas			
Lease State M		Well No. 3	Unit Letter D	Section 7	Township 18S	Range 34E	
Date Work Performed 10/17/63		Pool E. K. Queen			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Well drilled to a total depth of 4255 feet. Cone barrel stuck in bottom and well had to be plugged. Well plugged as follows: 25 sack cement 4255 - 4155; 25 sack cement 3000 - 2900; 25 sack cement 1900 - 1800; 25 sack cement 400 - 325; 10 sack cement 50 - 0. Steel marker erected.

Witnessed by Sam Hilburn	Position Superintendent	Company DOB Oil Properties, Inc.
------------------------------------	-----------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>John W. Runyan</i>	Name <i>Edward Smith</i>
Title	Position Agent
Date	Company DOB Oil Properties, Inc.