



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 10
Lease No. 062514-1
Unit G

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|---|---|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR..... |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... |
| NOTICE OF INTENTION TO ABANDON WELL..... | <u>Daily Logbook Report</u> |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 10, 1963

1. ~~Further information required.~~

Well No. 2 is located 100 ft. from [N] line and 100 ft. from [E] line of sec. 20

100 (1/4 Sec. and Sec. No.) 100 (Twp.) 100 (Range) 100 (Meridian)
100 (Field) 100 (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is NYA ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As of 7:00 A.M., 9-10-63: Drilling at 1745'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Am. American Petroleum Corporation

Address Box 41

100

By [Signature]

Title Area Superintendent