N. M. SH. CANS. COMMISSION

P. O. BOX 1080

Form 9-331 Dec. 1973

HOBBS, NEW MEXICO 88240

Form Approved. Budget Bureau No. 42–R1424

5. LEASE

## UNITED STATES

DEPARTMENT OF THE INTERIOR	NM-01/5//4
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME Plains Unit Federal 8. FARM OR LEASE NAME
1. oil well  other other  2. NAME OF OPERATOR  Dorchester Gas Corporation	9. WELL NO. 4-Y  10. FIELD OR WILDCAT NAME Lusk Strawn
<ul> <li>3. ADDRESS OF OPERATOR</li> <li>P. O. Box 96, Hobbs, New Mexico 88240</li> <li>4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> <li>AT SURFACE: 710' FSL &amp; 660' FWL</li> <li>AT TOP PROD. INTERVAL: AT TOTAL DEPTH:</li> </ul>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T. 19 S., R. 32 E.  12. COUNTY OR PARISH Lea New Mexico  14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	30-025-20518  15. ELEVATIONS (SHOW DF, KDB, AND WD) 3588 RDB
TEST WATER SHUT-OFF	irectionally drilled, give subsurface locations and not to this work.)*  Had severe paraffin buildup in tbg.  X 16' X 19' X 22' RHBC rod pump  Replaced 50 - 1" and 53 - 7/8" rod
couplings due to wear, ran 50 - 1" and 37 - put well back on production 05/25/82. Proc	7/8" rod guides. Set pump at 11222 Jucing 32 BOPD, 1 BWPD, 45 MCFPE
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
SIGNED Strue Callins TITLE District Engi	neer DATE <u>May 27, 1982</u>
ACCEPTED FOR RECORD space for Federal or State of	
conditions of approval JAN 191983	DATE
Ollif TO	