

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRORATION OFFICE	
OPERATOR	

A M E N D E D
NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

FORM C-103
(Rev 3-55)

HOBBS OFFICE O. C. C.

(Submit to appropriate District Office as per Commission Order)

Nov 15 3 40 PM '63

Name of Company DOB Oil Properties, Inc.				Address Box 953, Midland, Texas		
Lease State M	Well No. 3	Unit Letter D	Section 7	Township 18S	Range 34E	
Date Work Performed 10/9/63	Pool E. K. Queen			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations,
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Well spudded 10/18/63. 8-5/8 inch 36E J-55 casing set at 384 feet and cemented with 200 sack cement. Cement circulated to surface. Cement allowed to set 24 hours before testing 1000# pressure for 30 minutes with no drop.

Witnessed by Sam Hilburn	Position Superintendent	Company DOB Oil Properties, Inc.
------------------------------------	-----------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA



D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name 
Title	Position Agent
Date	Company DOB Oil Properties, Inc.