NO. OF COPIES RECEIVED] .		
DISTRIBUTION		HIDBS OFFICE O.C. BERVATION COMMISSION 6.C. 4 30 PH 36	Supersedes Old
SANTA FE		$\sum_{i=1}^{n} \sum_{j=1}^{n} \frac{1}{n} \sum_{i=1}^{n} \frac{1}{n} \sum_{j=1}^{n} \frac{1}{n} \sum_{i=1}^{n} \frac{1}{n} \sum_{j=1}^{n} $	C-102 and C-103
FILE	I NEW MEXICO ULL CONS	SERVATION COMMISSION	C. Effective 1-1-65
	-	4 on py	
U.S.G.S.	-		9 5a. Indicate Type of Lease
LAND OFFICE		-	State X Fee
OPERATOR]		
			B-1733
(DO NOT USE THIS FORM FOR PRO USE "APPLICAT	AND TICES AND REPORTS ON DPOSALS TO DRILL OR TO DEEPEN OR PLUG E	WELLS MACK TO A DIFFERENT RESERVOIR.	
			7. Unit Agreement Name
WELL WELL	OTHER-		-
2. Name of Operator			8. Farm or Lease Name
TEXACO Inc.			New Mexico 'L' State
3. Address of Operator			9. Well No.
P.O. Box 728 - Hobbs,	New Mexico 88240		8
4. Location of Well			10. Field and Pool, or Wildcat
	900 FEET FROM THE North		Undesignated
····· ···· ···· ······ ······ ······ ····		CINE AND FEET FROM	
THE East LINE SECTION	ON TOWNSHIP 8-S	34 5	
LINE, SECTION		RANGENMPN	•//////////////////////////////////////
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
X	3998' (D.F	F)	Lea
^{16.} Check			
	Appropriate Box To Indicate N		
NOTICE OF IN	ITENTION TO:	SUBSEQUEN	T REPORT OF:
	ا ب ے	<u> </u>	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS,	PLUG AND ABANDONMENT 🗙
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB	
		OTHER	
OTHER			
17 Dependen Dependen Germanden (

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Texaco has completed the following work on subject well:

TOTAL DEPTH 1490'

Spudded 15" Hole 11:00 A.M., April 12, 1964

Ran 1477' of 11-3/4" O.D. 23.72# Spiral Weld Casing and cemented @ 1490' w/800 sx Class 'C' 4% gel, plus 200 sx. Class 'C' neat with 2% Cacl. Plug @ 1417'. Cement circulated. Job Complete 7:00 A.M., April 16, 1964.

NOTE: Due to pipe condition, unable to drill below 826', pressure to 500#, and would not take fluid. Subject well was plugged and abandoned as follows:

- 1. Spot 50 sx cement plug from 738' to 826'.
- Spot 25 sx plug to 44'.
 Install dry hole marker, skid rig 15'.
- 4. Job complete 5:45 P.M., April 16, 1964.

18. I hereby certify that the information above is true and comple		
signed	Assistant District TITLE Superintendent	DATE JUIY 2, 1969
Le IAA	Carl C. Star Company of	* n a .
APPROVED BY Usles A - Coment	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		