

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MERIDIAN OIL INC.

3. Address and Telephone No.

P.O. Box 51810, Midland, TX 79710-1810 915-688-6943

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 27, T18S, R33E
1980' FSL & 990' FWL

N.M. OIL COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED

Expires: March 31, 1993

5. Lease Designation and Serial No.

LC 064944V

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal M # 1

9. API Well No.

30-025-21895 21893

10. Field and Pool, or exploratory Area

South Corbin Wolfcamp

11. County or Parish, State

LEA NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other

STATUS

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In response to the recently submitted sundry requesting continued temp. abandoned status which was approved on August 16, 1995. Please find attached the chart for the mechanical integrity test that was performed.

This lease outlines our East Corbin Delaware Unit. We are starting to see a response from the unit and there is the possibility that this lease be incorporated into the unit or be converted to injection to subsidize the flood. This evaluation should take approximately six (6) months depending on the response.

APPROVED FOR 12 MONTH PERIOD
ENDING 8/18/96

RECEIVED
AUG 3 12 03 PM '95

14. I hereby certify that the foregoing is true and correct

Signed

Title REGULATORY ASSISTANT

Date 8/21/95

(This space for Federal or State office use)

Approved by

Title

PETROLEUM ENGINEER

Date

10/5/95

Conditions of approval, if any:

1477 29 40
10 00 25 17
10 00 25 17

