

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-064944

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

Federal "M"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Corbin, Strawn South

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 27, T-18-S, R-33-E

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL [] GAS WELL [X] OTHER []

2. NAME OF OPERATOR Southland Royalty Company

3. ADDRESS OF OPERATOR 1100 Wall Towers West, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface

1980' FSL & 990' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3805' KB

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF []

FRACTURE TREAT []

SHOOT OR ACIDIZE []

REPAIR WELL []

(Other) []

PULL OR ALTER CASING []

MULTIPLE COMPLETE []

ABANDON* []

CHANGE PLANS []

SUBSEQUENT REPORT OF:

WATER SHUT-OFF []

FRACTURE TREATMENT []

SHOOTING OR ACIDIZING []

(Other) []

REPAIRING WELL []

ALTERING CASING []

ABANDONMENT* []

Status Report [X]

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

U.S.G.S. letter of August 2, 1978, requested status of well and future plans.

Present Status: Shut in. 5 1/2" casing set @ 13,325'. TD 13,406'; PBD 13,065' Morrow plugged and abandoned. Strawn perf exposed to well bore 12,302-12,316'.

- 8-8-78 RU swabbing unit. No pressure on tubing, swabbed dry, recovered 75 BW. Swabbed dry.
8-9-78 Swabbed 75 BW, swabbed down.
8-10-78 Swabbed 50 BW, fluid level 8500', swabbing down. RD swabbing unit.

Future Plan: Plug back, attempt recompletion to Wolfcamp - procedure to follow.

This approval of temporary abandonment expires 8-10-79

18. I hereby certify that the foregoing is true and correct

SIGNED Donald Craig

TITLE Engineer

DATE 8-16-78

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE 8-22-1978

U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO

RECEIVED

AUG 29 1978

OIL CONSERVATION COMM.

EDWARDS, N. M.