

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR

William E. Hendon, Jr

3. ADDRESS OF OPERATOR 601 N. Loraine, Suite 111
Midland, TX. 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 760' FNL & 1980 FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF

RECEIVED
OCT 21 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

(other) Weekly Report of 20 OCT '81

5. LEASE

NM 14000

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

New Mexico 35 Fed.

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Querecho

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 35, T-18-S, R-32-E

12. COUNTY OR PARISH

LEA

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3729 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was completed and kicked off. Flared intermittent gas while cleaning up completion fluid from wellbox. After not making any additional water, well was shut in at 8 AM MST, Friday, 16 Oct. '81. Testing began Monday, 19 Oct '81. SIWHP was 4227 psig by dead weight. Complete buildup, draw-down, and back-pressure test results will be supplied as soon as available.

Subsurface Safety Valve: Manu. and Type N/A Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Roger A. Chapman TITLE Oper. Engineer DATE 10-20-81

ROGER A. CHAPMAN

(This space for Federal or State office use)

APPROVED BY DATE 10-21-1981
CONDITIONS OF APPROVAL

**U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO**

*See Instructions on Reverse Side