

N. M. OIL & GAS COMMISSION
P. O. BOX 1980
HOBBSBURG, NEW MEXICO 88240
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well

2. NAME OF OPERATOR

William E. Hendon, Jr.

3. ADDRESS OF OPERATOR

601 N. Loraine, Suite 111

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 760 FNL & 1980 FEL

AT TOP PROD. INTERVAL:


AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) XX ☒

SUBSEQUENT REPORT OF:



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Hit cement @ 5506'. Drilling cement cut to 5618'. Washed & reamed to 6253'. Mud Wt. 9.5, Vis 37, pH 9.5. Continued reaming @ 7673'. Went easily to 8907'. 9-21-81 - Reaming. Maintained good mud and return. Mud Wt. 9.9, Vis 50, Cl 18/7000, pH 9.5, Wtr Loss 69. Expect to increase mud weight to 10.5 lbs per gal @ 11,000ft.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED ROBERT A. CHAPMAN TITLE Agent DATE 9-21-81

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

SEP 25 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO