

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |
| B-5659 | |

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Pennzoil Expl & Prod Company | 8. Farm or Lease Name Sinclair 6 State |
| 3. Address of Operator P.O. Drawer 1828, Midland, Texas 79702 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER D 660 FEET FROM THE South LINE AND 760 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 17-S RANGE 34-E NMPM. | 10. Field and Pool, or Wildcat Vacuum Wolfcamp, NW |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4119.7 GR | 12. County Lea |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|---|--|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/26/81 MI &RU unit. Dug pit and cleaned cellar.

5/27/81 ND tree, installed BOP and started POOH w/tbg.

5/28/81 Set 4-1/2" CIBP @ 10,315'. Dumped 35' cmt on top. Ran tbg to 10,000'. Displaced csg w/salt gel mud. Pulled up to 6020'. and spotted 15 sks class C cmt from 6020' to 5820'. WOC overnight.

5/29/81 WIH w/tbg to 6100'. Did not tag plg. Spotted another 15 sks class C cmt from 6020' to 5820'. WOC 4 hrs. WIH to 6300'. Did not tag plg. POOH w/tbg.

5/30/81 Set 4-1/2" CIBP @ 5900'. Dumped 35' cmt on top. Pressured csg to 2000#. Held OK. Ran Freepoint. Cut & pulled 4-1/2" csg from 4040'.

5/31/81 Shut down for Sunday.

6/01/81 WIH w/tbg & spotted 50 sks class C from 4090' to 3890'. WOC 4 hrs. Tagged plg w/tbg @ 3910'. POOH w/tbg. Ran Freepoint. Found 8-5/8" csg stuck @ 550'.

6/02/81 WIH w/tbg to 1660'. Spotted 35 sx from 1660-1545'. WOC 4 hrs. Tagged plg @ 1550'. POOH w/tbg. Cut & pulled 8-5/8" csg from 462'.

6/03/81 Finish pulling 8-5/8" csg. WIH w/tbg & spotted 100 sx cl C cmt from 510' to 400'. WOC 5 hrs. Tagged plg @ 405'. Pulled up & spotted 100 sx cl C cmt from 390'-260'. WOC overnight.

6/04/81 Tagged plg @ 280! POOH w/tbg. Dumped 10 sx surface & installed marker. Cleaned location. Job complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jess Culling TITLE Operations Engineer DATE 6/05/81

APPROVED BY Edwin W. Leary TITLE OIL & GAS INSPECTOR DATE MAR 22 1982

CONDITIONS OF APPROVAL, IF ANY: