

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-065710

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

PLAINS Unit Federal

8. FARM OR LEASE NAME

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

LUSK DELAWARE

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

28-19-32 NMPM

12. COUNTY OR PARISH

LEA

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL x 1980' FWL Sec. 28 (Unit H, SE 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3574 R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 12/13/69, 4 1/2" OD 9.5" J-55 Casing was set @ 4895' w/200
sq. Incon. * WOC appx 48 hrs. Perforated intervals
4719-29' w/ 2150' F. Acidized w/ 500 gal 15%.
Traced w/ 15000 gal oil + 17,500 # sand. Evaluated.
PT 1-2-70 Pump 30 bbl x 0 bbl 24 hrs. GOR 835.

x Test Casing w/ 2000 psi for 30 min. Test O.K.

TD = 4895'
PBD = 4893'

Comp 1-2-70

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE

1-5-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

OK - USGS-H
1- HSW
1- SUSP
1- RRY
1- MOBIL

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

JAN 7 1970

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO