

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)Form approved.
Budget Form No. 42-10424.

5. LEASE REGISTRATION AND SERIAL NO.

LC-065710

6. IF INDIAN, ALLOTMENT OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRILLING	7. UNIT AGREEMENT NAME PLAINS Unit Federal
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	9. WELL NO. 10
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL x 1980' FWL Sec 28 (Unit N, SE 1/4 SW 1/4)	10. FIELD AND POOL, OR WILDCAT Lusk Delaware
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28-19-32 NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3574' RDB	12. COUNTY OR PARISH 13. STATE LEA NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 11-25-69, 7 5/8" OD 24-26.4 # J-55, N-80 # H-40 Casing was set @ 2550' w/ 725 Sx 4% Gel + 2% CACK + 150 Sx Incon + 1% CACK. ALL SALT Saturated. Cement circulated. After HOC 18 hours, tested casing w/ 1500 psi for 30 min. Test O.K.

Reduced hole to 6 3/4" @ 2550 and resumed drilling.

19. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE 11-28-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DEC 1 1969

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

044 USGS-N
1-NSW
1-SUSP
1-RRV
1-MOBIC