NO. OF COPIES RECEIVED	NEW MEXICO OIL CONSERVATION COMMISSION		Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
	NEW MEXICO OIL CONS	SERVATION COMMISSION	
SANTAFE			5a. Indicate Type of Lease
FILE			State X Fee
U.S.G.S.	1		5. State Oil & Gas Lease No
	1		E-1635
OPERATOR			HIIIIIIIIIIII
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			7. Unit Agreement Name
1. OIL GAS WELL	OTHER- Dry		8. Farm or Lease Name
2. Name of Operator			Ark Junction
King Resources Company			g. Well No.
3. Address of Operator			
300 Wall Towers West, Midland, Texas 79701			10. Field and Pool, or Wildcat
4. Location of Well 4. Location of Well 660 FEET FROM THE South LINE AND 1830 FEET FROM			M Undesignated
UNIT CETTER			XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
THE East LINE, SECTION 30 TOWNSHIP 18-S RANGE 36-E NMPM.			
16. Check	15. Elevation (Show wheth 3829 GR Appropriate Box To Indicate INTENTION TO:	Nature of Notice, Report or O	12. County Lea Other Data NT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ABANDONMENT
	_[7	
OTHER		datas includ	ing estimated date of starting any propose
17. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent	details, and give pertinent dates, includ-	ing estimated date of starting any propose
4-27-70 - Cement p	lugs were set as follows		
11,227-1 10,800-1 10,300-1	1,327 with 25 sxs 50,900 with 25 sxs 50,400 with 25 sxs	,935-7,035 with 25 sxs ,604-5,704 with 25 sxs ,075-5,175 with 25 sxs (gging & abandonment. 11 Plugs were set as follo	bottom of 8-5/8" casing) 00' of 8-5/8" ows:

that the information above is true and complete to the best of my knowledge and belief. TITLE Drilling Foreman

325-405 with 25 sxs (bottom of 13-3/8" casing.

1075-1125 with 25 sxs

Surface with 10 sxs

Dry hole marker was placed at hole.