



## EQUIPMENT &amp; HOLE DATA

|                          |                    |      |       |
|--------------------------|--------------------|------|-------|
| Type Test                | M. F. E. OPEN HOLE |      |       |
| Formation Tested         | -                  |      |       |
| Elevation                | 4033               |      | Ft.   |
| Net Productive Interval  | -                  |      |       |
| Estimated Porosity       | -                  |      | %     |
| All Depths Measured From | KELLY BUSHING      |      |       |
| Total Depth              | 4865               |      | Ft.   |
| Main Hole/Casing Size    | 7 7/8"             |      |       |
| Rat Hole/Liner Size      | -                  |      |       |
| Drill Collar Length      | 620'               | I.D. | 2.25" |
| Drill Pipe Length        | 4187'              | I.D. | 3.82" |
| Packer Depth(s)          | 4836 & 4840        |      |       |
|                          |                    |      | Ft.   |

Sampler Pressure \_\_\_\_\_ 0 \_\_\_\_\_ P.S.I.G. at Surface

Recovery: Cu. Ft. Gas \_\_\_\_\_ - \_\_\_\_\_

cc. Oil \_\_\_\_\_ - \_\_\_\_\_ (TRACE)

cc. Water \_\_\_\_\_ - \_\_\_\_\_

cc. Mud \_\_\_\_\_ 1800 \_\_\_\_\_

Tot. Liquid cc. \_\_\_\_\_ 1800 \_\_\_\_\_

Gravity \_\_\_\_\_ - \_\_\_\_\_ ° API @ \_\_\_\_\_ - \_\_\_\_\_ ° F.

Gas/Oil Ratio \_\_\_\_\_ - \_\_\_\_\_ cu. ft./bbl.

|                         | RESISTIVITY  | CHLORIDE<br>CONTENT |
|-------------------------|--------------|---------------------|
| Recovery Water          | - @ - °F.    | - ppm               |
| Recovery Mud            | - @ - °F.    |                     |
| Recovery Mud Filtrate   | 5.0 @ 68 °F. | 108000 ppm          |
| Mud Pit Sample          | 4.4 @ 60 °F. |                     |
| Mud Pit Sample Filtrate | 2.8 @ 60 °F. | 124000 ppm          |

|                  |          |                             |             |
|------------------|----------|-----------------------------|-------------|
| Mud Type         | STARCH   | Wt.                         | 10.0        |
| Viscosity        | 39       | Water Loss                  | 5           |
| Resist. of Mud   | 4.4 @ 60 | °F <sub>2</sub> of Filtrate | 2.8 @ 60    |
| Chloride Content | 124000   |                             |             |
|                  |          |                             | C.C. °F PPM |

|          |  |
|----------|--|
| Remarks: |  |
|          |  |
|          |  |
|          |  |

Address Box 67; LOCO HILLS, NEW MEXICO 88255

Company ANADARKO PRODUCTION COMPANY

Well NEW MEXICO STATE "W" #1 Location -

Test Interval 4840' TO 4865' Test # 3 Date 2-27-73

County EA State NEW MEXICO

Technician MAXWELL (KERMIT) Test Approved By MR. DON LAYTON

Field Report No. 02357 C  
No. Reports Requested 7 (4x's)