## INCLINATION REPORT

OPERATOR John H. Hill	ADDRESS 1411 W. Ave, Suite 100, Austin, To	κ.
LEASE Shell State	WELL NO. 1 FIELD Underignated 78701	
LOCATION NW/2 of NE/2, Sec.	J 16. T-18S. R-34E, Lea County, New Mexico	

Depth	Angle Inclination	'degrees)	Displacement	Displacement Accumulated
438		1/4	1.9272	1.9272
938		1/2	. 4.3500	6.2772
1576		3/4	8.3578	14.6350
2079		3/4	6.5893	21.2243
2570	1		8.5925	29.8168
2763	1		3.3775	33.1943
3245	1		8.4350	41.6293
3460	1	1/4	4.6870	46.3163
3789	1		5.7575	52.0738
4022	1		4.0775	56.1513
4185 -		3/4	2.1353	58.2866
4401	1		3.7800	62.0666
4687	1		5.0050	67.0716

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Cactus Drilling Company Title:Ken Hedrick, Drilling Supt.

Affidavit:

Before me, the undersigned authority, appeared <u>Aen Hedrick</u> known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

(Affiant's Signature)

Sworn and subscribed to in my presence on this the // \_\_\_\_\_day of \_\_\_\_\_

19

Any containing the station and an 1974

Notary Public in and for the County

of Lea, State of New Mexico

Seal