

N. M. OIL & GAS COMMISSION
P. O. BOX 1980
ALBUQUERQUE, NEW MEXICO 88201

Form 3160-5
November 1983)
Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM-63026

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tonto West 7 Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat (Queen-Penrose Test)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

W $\frac{1}{2}$ Sec. 7, T-19S, R-33E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3665.3' G.R.

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-11-85 RU Logging Truck. TIH w/Gamma Ray CCL. Loggers TD @ 4628', PBTD @ 4637'. TIH w/perf guns & perf. as follows: 4424', 4425', 4426' & 4427' @ 1 J.S.P.F. (Penrose). Perf. Queen as follows: 4165', 4167', 4171', 4183', 4184', 4192' (Queen). RD Logging Truck. Tally & TIH w/144 jts. 2-7/8" tbg. to 4430'. Spotted 2 bbls. acid across perfs. Layed dn. 4 jts. of 2-7/8" tbg. Set pkr. RTTS @ 4328' K.B.M. Broke Penrose dn. @ 2200# psi. RU Swabb line & swabbed tbg. dry to seat nipple. RU Halliburton to complete acid job as follows:

500 gals. 15% NEFE

Dropped 10 Ball sealers (Well balled off)

Flushed w/27.8 bbls. 2% KCl wtr.

Avg. Press @ 2000# psi and Max. Press @ 3800# psi

Avg. RPM @ 3.5 bbls./min. and Max. RPM @ 3.6 bbls./min.

ISIP @ 1400# psi, 5 Min. @ 1100# psi, 10 min @ 700# psi

11-15-85 RU Halliburton. Spotted 2 bbls. 15% MCA Acid @ 4200' K.B.M. Layed dn. 5 jts. 2-3/8" tbg. Nippled dn. B.O.P. Set RTTS @ 4048'. Broke perfs @ 2200# psi. Swabbed tbg. to S.N. Completed acid job as follows:

CONTINUED ON PAGE 2 - OVER

I hereby certify that the foregoing is true and correct

SIGNED Lois N. Brown

TITLE Production Records

DATE November 20, 1985

(This space for Federal or State office use)

APPROVED FOR RECORD

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 22 1985

*See Instructions on Reverse Side



MURPHY OPERATING CORPORATION

ROSWELL PETROLEUM BUILDING

ROSWELL, NEW MEXICO 88201

MAILING ADDRESS
P. O. DRAWER 2648

TELEPHONE
505 623-7210

BLM Form 3160-5 - SUNDRY NOTICES AND REPORTS ON WELLS dated November 20, 1985 Page 2

TONTO WEST 7 FEDERAL #1
Wildcat (Queen - Penrose Test) RE-ENTRY
Federal Lease No. NM-63026

660' FNL & 660' FWL, (Unit Ltr. D) W¹/₂ Section 7, T-19S, R-33E,
Lea County, New Mexico

11-15-85 CONTINUED -

750 gals. 15% MCA acid
15 ball sealers (well balled off)

Max. press. @ 3600# psi	Avg. press @ 1800# psi
Max. RPM @ 4.2 bbls./min.	Avg. RPM @ 3.7 bbls./min.

Flushed w/2% KCl wtr. - 26.7 bbls.
Total bbls. to rec. - 44.7

ISIP 1000# psi - 5 min. 75# psi.

RD Halliburton.

RECEIVED
JAN 30 1987
OCD
HOBBS OFFICE