

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 067230

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

1860 Lincoln, Suite 1200, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980 FNL and 400 FWL

7. UNIT AGREEMENT NAME

Lusk (Seven Rivers)

8. FARM OR LEASE NAME

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Lusk (Seven Rivers)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3, T19S, R32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3668 GL

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☒

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/1 - 1/4/76 Waiting on Completion Unit.

1/5/76 Moving in Completion Unit.

1/6/76 GIH w/scraper on 2 3/8" tubing. WIH w/Bkr Model R pkr & set @ 3360. Tested csg. to 1600. OK. Tagged bottom @ 3854. Ran GR Corr log and perf'd 3827-37. Ran tbg. and pkr to 3674.

1/7/76 Swabbing well loaded hole w/oil. Attempted to reseal pkr. POH for new pkr.

1/8/76 Broke down perfs. @ 4000 psi, sand-oil frac'd w/9500# 20/40 sand. followed by 4000# 10/20 sand. AIR 8.4 bpm @ 4000 psi. TLTR 388 bo.

1/9/76 POH w/tbg. & pkr. WIH w/sand pump. Cleaned out 30' sand to 3836.

1/10 - 1/13/76 Cleaned out sand. to 3854. WIH with production tbg. SN @ 3816. Ran pump & rods and installed prod. facilities.

1/14/76 Recovering load oil.

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul F. Drake

TITLE

Production Clerk

DATE

Jan 21, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

