TO 0. C. C.

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9-331 Dec. 1973		1 10 (1 0.0.		Form Approved. Budget Bureau No. 42–R1424		
	UNITED	STATES	5. I	EASE		
	DEPARTMENT O	F THE INTERIOR	l N	M-077002		
GEOLOGICAL SURVEY				6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)			_J	7. UNIT AGREEMENT NAME		
reservoir, Use Form 9–331–C for such proposals.)			8. 1	8. FARM OR LEASE NAME		
1. oil gas well other			N	ellis Federal	B Gas Com	
			9. \	9. WELL NO.		
2. NAME OF OPERATOR			1		· · · · · · · · · · · · · · · · · · ·	
Amoco Production Company			10.	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR			B	Buffalo Penn Morrow		
P. O. Box 68, Hobbs, NM 88240				11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1980' FNL & 1980' FWL Sec. 5			ce 17	AREA		
				-19-33		
	ACE: (Unit F, S	E/4 NW/4)	12. (COUNTY OR PARISH	13. STATE	
AT TOTAL	PROD. INTERVAL:			ea	NM	
				API NO.	<u>.</u>	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			TICE,	·		
			15.	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
DECLIEST FO	R APPROVAL TO:	SUBSEQUENT REPORT C	_{.E} . <u>3</u>	726. RDB	1 F M	
TEST WATER		SOBSEQUENT REPORT C		50 @ E 1	NEW	
FRACTURE TI				一门冒护中		
SHOOT OR A	=	Ħ			, 1979 ⁻	
REPAIR WELL			(NO	TE: Report results of mi	ultiple completion to Xzone	
PULL OR ALT				change on Form 9-	330CAL SURV	
MULTIPLE CO	· · · · · · · · · · · · · · · · · · ·			e GEOLG	Ultiple completel EXZONE 330 CAL SURVEYZONE NEW MEXICO	
CHANGE ZON	IES 📙			U. JOBBS,	ME	

HOBBS, NEW MEXICO ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Drilled to a TD of 13689' and ran 5 1/2" casing set at 13689'. Cemented with 1650 SX Trinity Lite and 800 SX Class H Cement. Cement did not circulate. Temperature Survey found top of cement appx. at 215. Currently waiting on completion unit.

Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby certify that the foregoing is true and correct	_
SIGNED Kary Cox TITLE Admin. Supv. D	arman i
(This space for Federal or State office use)	OCCEPTED FOR RECORD
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	1070 (M)
0+4-USGS-H 1-HOU 1-Susp 1-BD	JUL 11 1913 U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO
*See Instructions on Payerse Side	U. S. GEOLOGIA MEXICO

*See Instructions on Reverse Side