Form 9-331 (May 1963)		UNIT STA	TFC	CHRASE ST	1 -		
(14.15 2000)	DEPA	RTMENT OF TH	E INTERIO	SUBMIT IN TRIPLIC (Other instructions or verse side)	Form app. Budget Br	ITESH No. 42 D1494	
GEOLOGICAL SURVEY					5. LEASE DESIGNATION AND SERIAL NO.  NM - 22613		
SUNDRY NOTICES AND REPORTS ON WELLS					6. IF INDIAN, ALLOT	TEE OR TRIBE NAME	
(Do not use th	is form for pr Use "APP	oposals to drill or to de LICATION FOR PERMIT	epen or plug back —" for such propo	to a different reservoir.			
OIL GAS WE'LL WELL OTHER  2. NAME OF OPERATOR					7. UNIT AGREEMENT	7. UNIT AGREEMENT NAME	
GULF OIL CORPORATION					8. FARM OR LEASE ?	8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR					Landsdale "D" Federal Co		
P. O. Box 670, Hobbs, NM 88240  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  At surface  At surface					7		
See also space 17 below.)  At surface					10. FIELD AND POOL, OR WILDCAT		
1980' FSL & 660' FEL					No. Lusk Mor	No. Lusk Morrow 11. SEC., T., R., M., OR BLK. AND	
- <b></b>	,00° F.DE	& coo. LET			SCAVEL OR AR		
4. PERMIT NO.	· · · · · · · · · · · · · · · · · · ·	15. ELEVATIONS (Sh	ow whether or or		Sec 4 -T19S-F	· ·	
		3666		GR, etc.)	12. COUNTY OR PARIS	H 13. STATE	
8.	Check			4 ) 1	Lea	NM	
	NOTICE OF IN	rention to:	indicate Natui	e of Notice, Report, o	or Other Data		
TEST WATER SHUT-O		PULL OR ALTER CASING			SUBSEQUENT REPORT OF:		
FRACTURE TREAT		MULTIPLE COMPLETE	' <del>                                    </del>	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING	<del></del>	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	ALTERING ABANDONM	<del></del>	
REPAIR WELL (Other)		CHANGE PLANS		(Other) 5111 CS	3 & cmt & fill	celler	
7 DESCRIPE URODOSER OF	2 COMPLETED (	Approximately (CI		(NOTE: Report resu Completion or Reco- cills, and give pertinent date and measured and true ver	ults of multiple completion mpletion Report and Log fo		
13,000' TD  Drld to (13, 5%" 17% csg:			e © 7:15 pr	n, 4-15-79. Ran 5646' of K-55) down complete @	330 & 1 cut jt	(12,9831)	
sx class "H"	w/1% CF	TR-2 & .5% Hala	of N_80 & d 9. Plug	5646 of K-55) down complete @	set @ 13,000'. 11:30 pm, 4-18-	Cmt w/1657	
Piped valves by Les Cleme	off csa	string above	ground leve	el & filled cella		nspected	
WOC over 24	hrs, tes	ted csg to 3000	0# for 30 m	in - held OK.	(5-3-79)		
						a le iin	
					n n	ש	
						979	
					U. S. GEOLOGICA HOBBS, NEW		
I hereby certify that t	he foregoing i	s true and correct			200		
SIGNED //.	· Sike	_///	rLE Area	CONTROL FOR REC	PATE 5-4-	<del>-</del> 79	
(This space for Federa APPROVED BY	l or State offi		1	MAY 8 19	19 (19)		
CONDITIONS OF APP	ROVAL, IF A	NY:	TLE	MAY 8 19	SURV DATE		
				L & GEOLOGION	MEXICO		

\*See Instructions on Reverse Side