O'BRIANT ENGINEERING SIG BUILDING OF THE SOUTHWEST MIDLAND, TEXAS 79701 915 - 683-3172 915 - 663-5511

FILE COPY

September 25, 1980

Mr. Charles Nearburg Chama Petroleum Company 5015 Tracy Street Dallas, Texas 75205

RE: OIL STRING CASING REPORT - 5-1/2" PENNZOIL FEDERAL NO. 1 LEA COUNTY, NEW MEXICO

Dear Mr. Nearburg:

Five and one half inch casing was run and cemented in your Pennzoil Federal No. 1 well on August 21, 1980. Details of this installation are as follows:

Casing Detail - Bottom to Top

1	-	Halliburton float shoe	1.00'	
1	-	Joint 5-1/2", 20#/ft., N-80,		
		LT & C	35.96'	
1	-	Halliburton float collar	1.00'	
		Joints 5-1/2", 20#/ft., N-80,		
		LT & C	117.64'	
1	-	Marker joint, 5-1/2", 20#/ft.		
		N-80, LT & C	10.00"	
4		Joints, 5-1/2", 20#/ft., N-80,		
		LT & C	161.37'	
1	-	Marker Joint, 5-1/2", 20#/ft.,		
		N-80, LT & C	10.50'	
7		Joints, 5-1/2", 20#/ft., N-80,	-	
		LT & C	279.17'	
1	-	Marker Joint, 5-1/2", 20#/ft.,		
		N-80, LT & C	10.50'	
41	-	Joints, 5-1/2", 20#/ft., N-80,		
		LT & C	1,616.59'	
39		Joints, 5-1/2", 17#/ft., S-95	1,522.36'	
		Joints, 5-1/2", 17#/ft., N-80,	-,	
		LT & C	7,519.91	
53		Joints, 5-1/2", 17#/ft., N-80,	,,01,071	
••		Buttress	2,160.15'	
			2/200123	
327	_	Total joints pipe run	13,446.15'	
		Marker joints cut off above GL	•	
5				
330	_	Total pipe run. Casing set @	13,429,15	GL
		KB to GL	18.00'	
		Casing set @	13,447.15	КВ
		annenil and f		