## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
BANTA FE		
FILE		
U.S.G.R.		
LAND OFFICE	1	
OPEGATOR		

-0. 07 \$07125 \$400146	OIL CONSERVA	TION DIVISION	
DISTRIBUTION	Р. О. ВО	X 2088	Form C-103 Revised 19-1-76
BANTA FE	SANTA FE, NEW	/ MEXICO 87501	Ket13e4 19-1-70
FILE			5a. Indicate Type of Leuse
U.S.G.R.			State X Fee
OPERATOR			5, State Oil 6 Gas Lease No. LG-5543
CLUID	V NOTICES AND DEPORTS ON	DUTLE	mmmmm/
USE "APPLICATE	Y NOTICES AND REPORTS ON POSALS TO CALL OF TO SEEPEN CA PLUG 1 10H FOR PERMIT - 11 FORM C-101) FOR SU	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	
OIL X WELL WELL	OTHER-		7, Unit Agreement Name
2. Name of Operator			8, Farm or Lease Name
GULF OIL CORPORATION			Lea "YH" State
3. Address of Operator			9. Well No.
P.O. Box 670, Hobbs, NM 88240			3
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER I 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM			Airstrip Wolfcamp
	*		
THE East LINE, SECTION	25 TOWNSHIP 18S	RANGE 34 E	4PM. (
mmmmm	15. Elevation (Show whether	DF RT. GR. etc.)	12. County
		5' GL	Lea
	**************************************		
Check A NOTICE OF IN	Appropriate Box To Indicate i тентон то:		Other Data ENT REPORT OF:
		· —	
PERFORM REMEDIAL WORK	PLUG AND ASANDON	REMEDIAL WORK	ALTERING CASING
TEMPOHARILY ASANDON	<u></u>	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB X	surrace
	LJ	OYNER	
OTHER		İ	
17. Describe Proposes or Completed Op	erations (Clearly state all pertinent det	ails, and give pertinent dates, inclu	ding estimated date of starting any proposed
work) SEE RULE 1703.			
11-3/4" H-40 42# ST&C CaCl <sub>2</sub> . Plug dn @ 1:3	A, 11-30-79. Reached 30 C csg (280'). Set @ 300 BOP, 11-30-79. Circ 25 midnight, 11-30-79. Te	". Cmt by Western $w/2$ sx cmt. WOC $10\frac{1}{2}$ hrs*.	250 sx Class "H" + 2%  Drld cmt & began drlg
. O-64 0			
* Option 2:	emt slurry 1.06 cu. ft./	eack	
	p of cmt slurry when mix		
Approx temp	min form temp $60^{\circ}$ .	ed oo r.	
Estimated (	emt strength @ time of c	so test 610 psi after	9 hrs.
Escinacea (	ome berengen & time or o	and the second second	
·			
1			
•			•
le. I hereby certify that the information	above in true and complete to the best	of my knowledge and belief.	
0010			
WP Vain 29	Are	a Drilling Superintend	lent pare 12-3-79
•16KT0	11101		
	y <b>*</b>		_
1541 / Ct. 2.			DTD 4 1070

RECEIVED

नी लाइन म्यालनाण