

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
Amoco Production Company
3. ADDRESS OF OPERATOR
P. O. Box 68 Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 660' FEL, Sec. 18
AT TOP PROD. INTERVAL: (Unit H, SE/4, NE/4)
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
- FRACTURE TREAT ☐
- SHOOT OR ACIDIZE ☐
- REPAIR WELL ☐
- PULL OR ALTER CASING ☐
- MULTIPLE COMPLETE ☐
- CHANGE ZONES ☐
- ABANDON* ☐
- (other) ☐

SUBSEQUENT REPORT OF:

- ☒
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

5. LEASE
NM-077002
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME *Federal*
Nellis ~~Federal~~ *C₇* Gas Com
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Buffalo Penn
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
8-19-33
12. COUNTY OR PARISH 13. STATE
Lea NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3677.9 GR

RECEIVED

MAY 23 1980
(NOTE: Report results of multiple completion or zone completion on Form 9-330.)U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 4-28-80 Abbott Bros. spudded a 17-1/2" hole with cable tools. Drilled to a TD of 95' and released cable rig. Moved in Big West Drilling Co. (Rig #22) and resumed drilling. Drilled to a TD of 450' and ran 13-3/8" casing set at 450'. Cemented with 500 SX Class C cement with 2% CACL. Plugged down 6:00 p.m. 5-6-80. Circulated 70 SX. WOC 26 hours. Tested casing with 1000# for 30 min. Test OK. Reduced hole to 12-1/4" and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Bob Davis TITLE Admin. Analyst DATE 5-19-80

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

0+4-USGS, H 1-Hou 1-Susp 1-BD

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

MAY 27 1980

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO