

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☐	OTHER- <u>INJECTOR</u>	7. Unit Agreement Name <u>N. HOBBS (G/SA) UNIT</u>
Name of Operator <u>SHELL OIL COMPANY</u>			8. Farm or Lease Name <u>SECTION 30</u>
Address of Operator <u>P. O. BOX 991, HOUSTON, TX 77001</u>			9. Well No. <u>222</u>
Location of Well UNIT LETTER <u>F</u> , <u>1470</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1395</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMPM.			10. Field and Pool, or Wildcat <u>HOBBS (G/SA)</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>3665' DF</u>			12. County <u>LEA</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER <u>COMPLETE AND PRODUCE SA ZONE II, III-U</u> ☒ <u>AND III-L</u>	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10-7-80: Perforate w/4 way squeeze gun, 4 holes @3718'. Set RBP @3716'; RTTS tool @3550'.
- 10-8-80: Pressure test RBP to 1500 psi - held OK. Spot 2 sx sand on top of RBP. Break down perms @2500 psi. Mixed and spotted 50 sx Class "C" cmt and squeezed 40 sx into formation; 10 sx cmt in csg.
- 10-9-80: Drld hard cmt 3571' - 3722'. Pressure test squeezed perms 3718 to 500 psi - held OK.
- 10-10-80: Perf'd 5 1/2" csg 4302' -4123'. Set pkr in blank pipe @4076' w/15' spacing and pressure test to 1500 psi - held OK.
- 10-12-80: Ran production equipment. Well complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR REG./PERMITTING DATE JULY 16, 1981

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: