

• Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-28083
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. SWD 119

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other **SWD**

2. Name of Operator
BASIN ALLIANCE LLC

3. Address of Operator
P.O. Box 1378, Hobbs, NM 88241

4. Well Location
Unit Letter **G** : **2310** feet from the **North** line and **2310** feet from the **EAST** line
Section **33** Township **18S** Range **36E** NMPM **LEA** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3806 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: **Repair tubing leak**

OTHER: ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/25/01 MOVED Rig in, Rigged up. Nipple down wellhead. UNSOATED PACKER. Pull 56 jts found hole in tubing. Pulled rest of tubing, find 6 more bad jts. Rig up testers, tested Hbg to 5000 psi. Above the slips. Find 1 more bad jt. Replaced a total of 8 bad jts. Rig down testers nipple up wellhead. Pump 73 bbls PKR FL. unset PKR w/ Pump 137 BBLs. SET PKR w/18000 Compression Flange well up Load CASING w/70 more bbls. Test to 300 psi.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **Hugo Naegele Jr.** TITLE **Member** DATE **4-26-01**

Type or print name **Hugo NAEGELE JR.** Telephone No. **397-5989**
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

ICS





