

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL CONS. COMMISSION
B.O. BOX 607
MARBLE FALLS, TEXAS 78654
88240

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-19448

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

DOROTHY

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

UNDES. EK BONE SPRINGS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 25, T. 18 S., R. 33 E.

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

C. W. TRAINER

3. ADDRESS OF OPERATOR

ROUTE 3, BOX 607, MARBLE FALLS, TEXAS 78654

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

554' FSL AND 554' FEL OF SECTION 25

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3855 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SETTING SURFACE CASING

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

XX

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-31-83: MOVED IN CABLE TOOL RIG AND SPUDDED WELL ON 10-31-83. COMMENCED DRILLING WITH CABLE TOOLS.

3-6-84: MOVED IN ROTARY RIG AND COMMENCED DRILLING WITH ROTARY.

3-7-84: RAN AND SET 13-3/8", 54#, K-55 CASING IN 17-1/2" HOLE AT 370 FEET. CEMENTED WITH 375 SACKS OF CLASS "C" CEMENT WITH 2% CACL. CEMENT DID NOT CIRCULATE. RAN 1" TUBING DOWN ANNULUS TO 135' AND PUMPED IN 100 SACKS OF CLASS "C" CEMENT WITH 2% CACL. CIRCULATED 10 SACKS OF CEMENT TO PIT. CEMENT JOB WITNESSED BY BLM REPRESENTATIVE.



18. I hereby certify that the foregoing is true and correct.

SIGNED

Arthur R. Brown

TITLE

Agent

DATE

3-16-84

(This space for Federal or State use)

APPROVED BY

PETER W. CHISTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 13 1984

*See Instructions on Reverse Side

RECEIVED

APR 17 1984

C. C. B.
TREAS. OFFICE