WELL NAM	E AND NUMBER _	Lusk Seven Rivers	Unit # 8	
LOCATION	Unit #8 (Give Unit	, Section, Township	and Range)	
OPERATOR	Maralo, Inc.			

•---

DRILLING CONTRACTOR Tinsley & Son Drlg. Corp.

.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation test and obtained the following results:

	Degrees @ Depth	1	Degrees @ Depth		Degrees @ De	pth
	370	-	1			
	879	-	l <sup>1</sup> 2			
	1337		14			
	1836	· · .	$1^{1}_{2}$			
	2360		11/4			
	2885	, ,	11/4			
	3076	_	1 3/4			
	. 3482	-	1 3/4			
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	4059	-	2	,	<b></b>	
	·	_				
. •		_				
		_			<u> </u>	
		_			. • <u></u>	
		_				
:			Drilling Contra	ctor _	Tinsley & Son	Drlg. Corp.
	•		4	By _	fiel Liel	~~~~~
Subscribe	ed and sworn to b	efore me t	this day	of	anuary	19 <u>85</u>
,				(	Votary Public	allison
		1-10-	88	Ê	Tren	Jeps
My Commi	sion Expires:	/ / 7 -	00	Coun	ty	State

FEB 18 1985

,

RECEIVED