Form 9–331 Dec. 1973	Form Approved. 은 단화에 per Busheu Ng: 설문에 1424
UNIT. STATES	5. LEA BUY O O B B
DEPARTMENT OF THE INTERIOR	3.3 65 303 288 3 5 5
GEOLOGICAL SURVEY	6. IF INDIAN, ALL THE OR TRIBET AME
	5 d a 3 d a
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEM AND AME OF GOOD
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	
4 .1	8. FARM OR LEAST HAME 2 25 5
well X well other	O WELL NO STORY
2. NAME OF OPERATOR	9. WELL NO. Same is a second of the same is a second o
El Paso Exploration Conpany	10. FIELD OR WIGHT ANAME. 글 등 설
3. ADDRESS OF OPERATOR	Mescalero Esgarpe
1800 Wilco Bldg., Midland, TX 79701	11. SEC., T., R., 福吉隆底BLK. AND 新華安全 OR
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	00
AT SURFACE: 1,980' FSL & 1,980' FWL	12. COUNTY OR PARKS 135 STATE 2
AT TOP PROD. INTERVAL:	Lea Sasse s and
AT TOTAL DEPTH: 8,920'	14. API NO. 3 2 2 2 3 3 8
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	bed base
ALFORT, OR OTHER DATA	15. ELEVATIONS (SHOW DE KOS AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	34 , 990' SIE 5 3
TEST WATER SHUT-OFF	on on one of the second of the
FRACTURE TREAT SHOOT OR ACIDIZE T	The state of the s
REPAIR WELL	(NOTE: Report regults of anultiple completion or zone
PULL OR ALTER CASING MULTIPLE COMPLETE MULTIPLE COMPLETE	change of English D 220 V
CHANGE ZONES	Siedo Siedo Siedo Tanan Tanan Tanan Tanan Tanan Tanan Tanan
ABANDON*	South So
(other) Cement casing \overline{X}	ZHOSTAVITENE OFFICE OFF
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,	
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
·	မြည်းမြိများ ရှိ စည်းချစ် မည်းမြိများ
December 15, 1985, operator ran 218 jt	ts 5 1/2" 13 # set @ 38; 920
feet RKB. Cement w/200 sxs Halco lite	e w/10# sælt 38 Halað 22
plus 200 sxs 50-50 Poz Mix Cl "H" 2% of Survey, top of cement 6,600'. Waiting	gel 5% Halad 9 Ran Temperature g on completion.
all voy, cop of comene o, ooo . Walting	g on completaon. Was a maga
and the second of the second o	를 가고 있다.
£u.€	# # # # # # # # # # # # # # # # # # #
DEC 80 198 5	
1980-00- 1985	전 및 최 의 의 교육 등 전 등 한 경 를 받는 것 같다.
CAST TELEVISION BOOK	
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the soregoing is true and correct	
SIGNED STATE ST. Staff F	Engr.oate December 23 1985
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE 7 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	기계를 하는 사람들이 가득하는 사람들이 되었다.
	The second secon