

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
EL PASO EXPLORATION COMPANY
3. ADDRESS OF OPERATOR 75701
1800 WILCO BUILDING, MIDLAND, TX
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1,980' PS & 1,980' FWL
AT TOP PROD. INTERVAL
AT TOTAL DEPTH: 8,800'
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF REPORT.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	☐
FRACTURE TREAT	☐
SHOOT OR ACIDIZE	☐
REPAIR WELL	☐
FULL OR ALTER CASING	☐
MULTIPLE COMPLETE	☐
CHANGE ZONES	☐
ABANDON*	☐
(other) Cement Casing	X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give latitude/longitude and measured and true vertical depths for all markers and zones pertinent to this work.)

November 19, 1985, operator ran 14 its 13 1/8" 61# casing set at 555 feet RFB. Cement with 573 sxs Cl "C" 2% cr, 1/4#/sxs Floccle 14.8 ppg circ 20 sxs to surface. November 21, 1985, operator ran 22 its 8 5/8" 24# & 12# casing set at 1,278 feet. Cement with 660 sxs Halco Lite, 154/sxs salt, 1/4#/sxs Floccle 12.8 ppg plus 300 sxs Cl "C" 2% cr, 1/4#/sxs Floccle, 14.8 ppg, circ 20 sxs to surface.

ACCEPTED FOR RECORD

Gurd
 DEC 3 1985

Subsurface Safety Valve: Many, and Type

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* *[Signature]* JUNE Sr. Staff Engr. DATE December 27, 1985

_____ (If no space for Federal or State office, use)

APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL IF ANY _____

RECEIVED
TFC 4-1985
NOV 14 1985