

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NM - 17087, 17807
2. NAME OF OPERATOR Marshall & Winston, Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 310 West - #10 Desta Dr., Midland, Texas 79705	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 610' FSL & 760' FWL, Sec. 23, T18S, R32E	8. FARM OR LEASE NAME Querecho Federal
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DT, RT, GR, etc.) GL = 3765.3	10. FIELD AND POOL, OR WILDCAT Undes. Querecho Federal Upper.
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA B.S.
	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	Initial Report <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 12/31/85 MI Landis Drilling Company, Rig #1 & drld. 17½" hole to 354'. Set new 13 3/8", 68#, K-55, ST&C at 354'. Cmt'd. w/385 sxs. Class "C" + 2% CaCl. Circulated cement to surface. BLM witnessed.
- 1/04/85 Drld. 11" hole to 3047'. Set new 8 5/8" csg as follows: (0-1762'), 24#, J-55, ST&C, (1762-2587'), 28#, J-55, ST&C, (2587-3047'), 32#, J-55, ST&C. Cmt'd. w/1275 sxs. lite followed by 200 sxs. Class "C". Circulated 95 sxs. to surface. BLM witnessed.
- 1/27/85 Drld 7 7/8" hole to 9580'. Logged & set cement plug from 8917-8743'. Ran 5 1/2" csg as follows: (0-1709'), 20#, N-80, LT&C, (1709-7323'), 17#, K-55, LT&C, (7323-8565'), 17#, N-80, LT&C. Cmt'd. w/1250 sxs. Class "H" 50/50 Poz. By temperature survey, TOC= 3350'.

ACCEPTED FOR RECORD

Gov
FEB 19 1986

CARLSBAD, NEW MEXICO

I hereby certify that the foregoing is true and correct

SIGNED *Clarence R. Chandler*

TITLE Vice President

DATE 2/14/86

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE