

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Mewbourne Oil Company

3. Address and Telephone No.

P.O. Box 5270 Hobbs, New Mexico 88241 (505) 393-5905

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1950' FSL & 1980' FWL
Sec. 23-T18S-R32E

5. Lease Designation and Serial No.

NM-0554967

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Government "K" #2

9. API Well No.

30-025-29749

10. Field and Pool, or Exploratory Area

Querecho Plains
Upper Bone Springs

11. County or Parish, State

Lea County, N.M.

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other Recompletion
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☒ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 8-10-92 RU well service rig. POOH w/rods & tbg. RIH w/pkr. to 4000'.
8-11-92 Set pkr. @ 4900'. Established injection rate of 2 BPM & 1000#. Mixed & pumped 150 sx. Class "C" cement. Did not squeeze. Waited 4 hrs. Mixed & pumped 75 sx. Class "C" cement. Obtained 3000# squeeze across Delaware formation @ 4859'.
8-12-92 RIH to drill out cement. Cement still green. Shut down.
8-13-92 Drilled out cement across Delaware formation and pressured to 1700#. Held ok. RIH & drilled out CIBP @ 8340', opening Upper Bone Springs perforations.
8-14-92 Ran Seismic Fracture Dimension Survey to determine frac orientation.
8-16-92 RIH w/tbg. & POOH inspecting tbg. w/scanalog inspection tool.
8-17-92 RIH w/Otis permalatch packer & set @ 8260'. Pressured csg. to 1000#. Held ok. RD MO well service rig. Well ready for injection.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Engineer

Date

August 27, 1992

This space for Federal or State office use.