

Yates Petroleum Corporation  
Lusk "AHB" Federal #4  
C 35-T19S-R32E

Attachment A

Page 1

III. Well Data

A. 1. Lease Name/Location:

Lusk "AHB" Federal #4  
C 35-T19S-R32E  
660' FNL & 2310' FWL

2. Casing Strings:

a. Present Well Condition

13 3/8", 54.5#, J55 @ 1142' w/950 sx  
8 5/8", 32#, J55, HC 80 @ 4465' w/2175 sx  
5 1/2", 17 & 15.5#, J55 @ 7860' w/825 sx  
TOC - 4265' CBL  
TD @ 7860'  
Perforations (Delaware): 4733'-4742', 4902'-4908',  
5034'-5045', 5121'-5138', 6384'-6401', 7647'-7678'

Present Status: Unsuccessful, uneconomic completion in  
the Delaware (5 BOPD/400 BWPD).

3. Proposed well condition:

Casing and perforations same as above.

3 1/2" 9.3 J55 or 2 7/8" 6.5 J55 plastic-coated injection tubing @ 4650'.

4. Propose to use Guiberson or Baker plastic-coated or nickel-plated packer  
set at 4650'.

B. 1. Injection Formation: Delaware Sand

2. Injection Interval will be through perforations from approximately  
4733'-7678'.

3. Well was originally drilled as a Delaware Sand oil well. Well will be  
Delaware Sand water disposal well (4733'-7678') when work is completed.

4. Perforations: 4733'-4742', 4902'-4908', 5034'-5045', 5121'-5138', 6384'-6401',  
7647'-7678'