

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P.O. Box Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31132
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-2146
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	114
9. Pool Name or Wildcat	VACUUM GLORIETA

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>B</u> ; <u>280</u> Feet From The <u>NORTH</u> Line and <u>2080</u> Feet From The <u>EAST</u> Line Section <u>1</u> Township <u>18S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3993' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐  
 OTHER: ☐

**SUBSEQUENT REPORT OF:**

- REMEDIAL WORK ☒ ALTERING CASING ☐  
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER: add Perf SET CIBP @ 6010' ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/23/96 - 12/28/96

1. MIRU. Installed BOP. TOH w/ subpump.

2. Set 5 1/2" CIBP @ 6010'. TIH w/ treating pkr on 2 7/8" tbg and set pkr @ 5833'.

3. Acidized Upper Paddock perms from 5944'-5992' w/ 2000 gals 15% HCL. Max P = 1100#, AIR = 4.9 BPM. SI for 48 hrs.

4. Swabbed back load. TOH w/ treating pkr. Left CIBP @ 6010' in hole.

5. TIH w/ subpump & returned well to production.

OPT 1/14/97 BY SUB PUMP: 42 BOPD, 1346 BWPD, 26 MCFD

(INTERNAL TEPI STATUS REMAINS PM)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engr Asst

DATE 1/17/97

TYPE OR PRINT NAME Monte C. Duncan

Telephone No. 397-0418

(This space for State Use)

APPROVED BY Monte C. Duncan TITLE Engr Asst

DATE JAN 29 1997

CONDITIONS OF APPROVAL, IF ANY: