

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
5. Lease Designation and Serial No.
NM0997/LC069420
6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MERIDIAN OIL INC.

3. Address and Telephone No.

P.O. Box 51810 Midland, TX 79710

915-688-6943

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC. 8 & 17

T18S, R33E

7. If Unit or CA, Agreement Designation

8. Well Name and No. WEST CORBIN

FEDERAL LEASE

9. API Well No.

10. Field and Pool, or Exploratory Area

CORBIN FIELD

11. County or Parish, State
LEA COUNTY, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other: REQUEST TO VENT GAS

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose of Water

DUE TO PLANT TURNAROUND

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is functionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

WE RESPECTFULLY REQUEST TO VENT THE CASINGHEAD GAS ON THE BELOW WELLS DUE TO THE SCHEDULED PLANT TURNAROUND OF THE CONOCO FACILITY LOCATED AT MALJAMAR, NM FROM 12 AM APRIL 18, 1994 THRU 12 AM APRIL 21, 1994. THIS REQUEST IS MADE TO ALLEVIATE CAUSING DETRIMENTAL DAMAGE AND LONG TERM PROBLEMS TO THE WELLS' PRODUCTION BY SHUTTING THE WELLS IN DURING THE PLANT PROCEDURES.

WEST CORBIN FEDERAL # 11 BATTERY CONSISTING OF THE FOLLOWING:

WEST CORBIN # 26 SEC. 8 LC069420
WEST CORBIN # 11 SEC. 8 NM 0997
WEST CORBIN # 28 SEC. 17 NM 0997
WEST CORBIN # 14 SEC. 17 NM 0997

A HYDROGEN SULFIDE TEST WAS PERFORMED BY INDIAN FIRE AND SAFTY ON THE WELLS AND BATTERY ON JANUARY 10, 1994. THIS TEST WAS DONE WITH 4LL SENSIDYNE TUBES AND THE LEVEL OF H2S WAS 0 PPM.

14. I hereby certify that the foregoing is true and correct

Signed

DONNA WILLIAMS

Title PRODUCTION ASSISTANT

Date 4/5/94

(This space for Federal or State office use)

Approved by Signed by Adam Salameh

Title Petroleum Engineer

Date 4/22/94

Conditions of approval, if any: