CONTACT RECEIVING **BLM Roswell District** Form 3160-5 Modified Form N NM060-3160-4 STATES OF COPIES REQUIREL (July 1989) DEPARTMENT OF THE INTERIOR (Other instruction es on reverse LEASE DESIGNATION AND SERIAL NO. (Formerly 9-331) BUREAU OF LAND MANAGEMENT NM-21172 IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS n for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposale.) 7. UNIT AGREEMENT NAME OTHER API NO. 30-025-31575 NAME OF OPERATOR FARM OR LEASE NAME MERIDIAN OIL INC PERCHA 15 FED. COM ADDRESS OF OPERATOR 3a. AREA CODE & PHONE NO. WELL NO. 9. P.O. Box 51810, Midland, TX 79710-1810 915/688-6906 3 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) FIELD AND POOL, OR WILDCAT 10. SOUTH CORBIN WOLFCAMP At surface L. 1830' FSL & 660' FWL, SEC. 15, T18S, R33E SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 15, T18S, R33E 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 30-025-31575 3880 'GR LEA NM Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. NOTICE OF INTENTION TO SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERNIC CASING SHOOT OR ACIDIZE ARANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE DI ANS (Other) SET INTERMEDIATE CSG (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 7/29/92 - DRILLED 12 1/4" HOLE TO 3058'. RAN 67 JOINTS 8 5/8" 28# K-55 BTC CASING SET AT 2955'. CEMETED WITH 1000 SACKS "C" LITE PLUS 6% GEL PLUS 9 PPS SALT PLUS 1/4 PPS FLOCELE. TAILED IN WITH 250 SACKS CLASS "C" PLUS 2% CaCl2. CIRCULATED 200 SACKS TO PIT. WAITED ON CEMENT 18 HOURS. PRESSURE TESTED 8 5/8" CASING AT 1500 PSI FOR 30 MIN. - OK. USED 4 CENTRALIZERS.

3 992

AR-

*See Instructions on Reverse Side