
	er .		N.M. Oil Con	° . a		
Form 3160-5			P.C 1980			
(June 1990)	DEPARTME	TTED STATES NT OF THE INTERIOR	Hobb., NM 882	Expires: March 31, 1993		
	BUREAU UP	LAND MANAGEMENT		5. Lease Designation and Serial No.		
	SUNDRY NOTICES	AND REPORTS ON WELLS	S	NM 26692 6. If Indian, Allottee or Tribe Name		
Do not use	this form for proposals to c Use "APPLICATION FO	rill or to deepen or reentry to a DR PERMIT—" for such propos	a different reservoir.	N/A		
	SUBMI	T IN TRIPLICATE		7. If Unit or CA, Agreement Designation		
I. Type of Well				N/A		
X Oil Gas Well Other 2. Name of Operator				8. Well Name and No.		
J. M. Huber Corporation				Federa] ''26-A'' #2		
3. Address and Telephone No.						
1900 West Loop South, Suite 1600, Houston, TX 77027 (713)871-4400 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				30-025-33993 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Corbin South - Oueen		
1980' FSL and 1980' FWL, Sec. 26, T18S-R33E Lea County, New Mexico				11. County or Parish, State		
				Los Cauntas N. H.		
12. CH	ECK APPROPRIATE BOX	s) TO INDICATE NATURE O	F NOTICE, REPOR	Lea County, New Mexico		
	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORTIVE OF SUBMISSION TYPE OF ACTION			, on onich bata		
	Notice of Intent	Abandonment		Change of Plans		
ראו	Subsequent Report	Recompletion		New Construction		
	Subsequent Report	Plugging Back		Non-Routine Fracturing		
Final Abandonment Notice		Casing Repair Altering Casing		Water Shut-Off		
		Other_Surfac	ce Casing	Conversion to Injection Dispose Water		
				(Note: Report results of multiple completion on Well		
 Describe Propos give subsur 	ed or Completed Operations (Clearly state al face locations and measured and true vertice	pertinent details, and give pertinent dates, incli al depths for all markers and zones pertinent t	uding estimated date of starting ar	Completion or Recompletion Report and Log form.) ny proposed work. If well is directionally drilled.		
//3/9/	- Spud well @ 3:15 P.M					
	7/3/97 - Run and cement 8 5/8" casing in 12 1/4" hole. Set 8 jts. 8 5/8", 23#, M-50,					
7/4/97	sign squaring at JJU. Flaced one centralizer in middle of shoe total					
	contradized across each of the 1st. and 3rd 5th and 4th college of					
	w/230 sx Halliburton Premium Plus cement, w/1.6% CaCl. Plugdown @ 1:35 A.M. 7/4/97. Cement did not circulate. WOC 4 hrs. Tagged up 16' below surface.					
	- amp 5: 3x cement tillu 1, CIFC 1/ SX to Dit. RIM witnessed coment ich					
	THE MIDDLE COLLEZ.					
7/4/97	WOC total of 14.75 h	rs. Test BOP and csg to	o 1905 psi for 3	0 min. Held o.k.		
			MENTED DED DECOM	on T		
		l AG	CEPTED FOR PECOF	!		



14. I hereby certify that the foregoing is true and correct Signed Amale Alauman	Donald E. Lanman, P.E. Title Sr. Staff Petroleum Engineer	Date7/18/97
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	Date